Project 1	Stakeholder Comments	Stakeholders	time of response	Date of response	Complaint source	Time of complaint	te of complaint
The proj build a r	The stakeholder complained about demolition of Parramatta War Memorial Swimming Pool and enquired if a war memorial will be built as part the new stadium.	[name removed]	unie of response	10/09/2018	Phone call		28/08/2018
t Graffiti i	Stakeholder advised found graffiti on southern part of the Stadium site.	[name removed]		25/06/2018			25/06/2018
operato	The stakeholder sent an email to 2GB on 15 March and copied in the project enquiries email address.The stakeholder complaint about the seating application for the Western Sydney Stadium.	[name removed]		20/03/2018	Email		15/03/2018
The proj n to confir given its	The stakeholder alleged that his car had been damaged, due to rubble in a green shopping bag on Victoria Road, to the north of the project site two weeks earlier.	[name removed]		2/02/2018	Phone call		30/01/2018
The pro o parked i Manage stakeho with the	The Assistant Principal of Our Lady of Mercy contacted the project team to advise there were two big trucks parked at Ross St. at 8am on Friday 27 October.	[name removed]	1:30 PM	27/10/2017	Phone call	1:30 PM	27/10/2017
The pro	The stakeholder raised concerns that the artist impressions shown on the shadecloth placed on the boundary fence did not reflect the cultural diversity of the area.	[name removed]	3:30 PM	21/04/2017	Email	7:00 PM	17/04/2017
ed Addition The stal with the	Stakeholder complained about dust being generated from demolition activities.	Parramatta Swimming Centre management	1:45 PM	13/03/2017	Phone call	11:15 AM	13/03/2017
n activities e onsite m revised	Vice-President of Camwest, raised concerns with the size of the directional signage installed, the location of the signage and requested for additional signage to be installed. The stakeholder also queried the consultation/communication activities undertaken to notify people of the changes.	[name removed]	12:05 PM	15/02/2017	Email	10:48 AM	13/02/2017 0:00
out side of t stakeho Direction stadium to maint	Vice-President of Camwest, a local cycling advocacy group, emailed the project team with concerns about the site boundary fencing installed and lack of communication to park users about the access changes including directional signage around the park and stadium precinct. The stakeholder also raised concerns about the safety of alternate routes for cyclists.	[name removed]	9:15 PM	7/02/2017	Email	9:15 PM	5/02/2017
f The pro receivin redunda stakeho Fencing for off cr A call to action ta	Stakeholder commented that there were off cuts of fencing materials in Parramatta Leagues club car park. Stake holder was concerned that it could cause a puncture to the cars parked.	[name removed]	10:45 AM	4/02/2017	Phone call	10:45 AM	4/02/2017

eam Response

ect team advised that there are no plans at the moment to eplacement war memorial.

nmediately removed.

ect team passed enquiry to Venues NSW as future s of the stadium.

ect team investigated the alleged incident, but was unable n that the rubble referenced was from the project site location.

ect team briefed all sub-contractors that no trucks are to be n this location, and were reminded of the Traffic ment Plan that must be followed at all times. The der was advised of the actions taken, and was satisfied butcome.

ect team confirmed that there was no intention to exclude liversity from the artist impressions used on the th, and that this would be considered in future artist ons created for the project. No further comments were from the stakeholder.

al dust supression measures were implented immediately. eholder was notified of the actions taken and was satisfied outcome.

ect team confirmed the consultation and communication undertaken to inform the community of the changes. An eeting was offered to the stakeholder to go through the arrangements.

n how cyclists and pedestrians can access the northern ne stadium including a map was provided to the der.

al signage showing the revised access around the was installed. Note that an internal fence line was installed ain access along the north side of the stadium without pedestrians or cyclists to travel through the Leagues Club

ect team visited site and the car park immediately after the complaint and confirmed there was little to no nt materials in the car park that could cause the issues the der raised.

contractor was briefed to check to check perimeter fencing ts etc. on public side before they leave work areas. stakeholder was made the afternoon to advise of the ken and was satisfied with the outcome.